B-2758

POPPLETON HISTORIC STUDY

mag1#0427585404

Block

Lot

Address

94,3

18-27

125-141 S. Poppleton Street

Approximate age

1800-1845

1845-1860

1865-1880

1880-1896

1896-on

Rating Architectural		Condition			
A	Significant-save	good	fair	poor	bad
В	Quality-Indiv./groups-save	good	fair	poor	bad
(c)	Important to street/groups	good	fair	poor	bad
D	Insignificant/detrimental	good	fair	poor	bad

Notable features:

appropriate.

As soon as one turns the corner from Pratt into Poppleton, the houses are better, though by no means well kept. This is an interesting terrace with variety of roof line, generally following the rising contours as it steps up the hill. They should be rehabilitated before they slip into further disrepair. There are no dramatic details but some ironwork. The two set back houses are worth noting as old or in an early shed roof vernacular and quite charming. Number 137 is very well kept. It is half of a gable house, the rest being behind number 135 (as was the case at 888-888% W. Lombard Street). Original ironwork remains at 123; 139 is formstoned.

Environmental context: Lot at 141 (on corner of Pratt) is vacant, but no vacancies in this entire block face. The empty corner lot has a large billboard which should not be; a mini-park, trees and a bench would be more appropriate (as is in process at HCD). There is one nice old Linden tree but it needs company. The entire corner of the block opposite has been cleared; the park-use planned by HCD for this corner seems



B-2758 125-141 S. Poppleton Street Block 253 Lot 018-027 Baltimore City Baltimore West Quad.

